## CORNER RECORD Document Number \_\_\_\_\_ BURBANK County of Los Angeles, California Brief Legal Description RIVERSIDE DR. & GRIFFITH PARK DR.- C/L MONUMENT PRESERVATION **CORNER TYPE** COORDINATES (Optional) Govt. Corner Control П NAD27 □ NAD83 Meander П Property NAD83 Epoch \_ Rancho Elev. Other NGVD29 □ Vert. Datum: NAVD88 Date of Survey May 1, 2003 Metric Meas. Units: Imperial Left as found Found & tagged Established Corner -Reestablished X Rebuilt Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: distances measured horizontal: A description of the physical condition of the monument as found and as set or reset: see plat; SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance May 31, 2003 with the Land Surveyors' Act on P.L.S. or R.C.E. No. \_\_\_\_\_ 5691 COUNTY SURVEYOR'S STATEMENT This Corner Record was received \_\_\_\_\_ and examined and filed \_\_\_\_\_\_ Signed \_\_\_\_\_ P.L.S. or R.C.E. No.

County Surveyor's Comment